


DOUBLE ENDED RAM MOUNTING POSITION FOR CORRECT GEOMETRY.


THE TIE ROD END MUST BE IN-LINE WITH
THE RAM SHAFT WHEN AT FULL LOCK POSITION(S).

FULL RAM EXTENSION INCORRECT



THIS IS INCORRECT.
THE TIE ROD END IS NOT IN-LINE
WITH THE RAM SHAFT AT
FULL LOCK POSITION.

FULL RAM EXTENSION CORRECT



THIS IS CORRECT.
THE TIE ROD END IS IN-LINE
WITH THE RAM SHAFT AT
FULL LOCK POSITION.

IF YOU HAVE ANY QUESTIONS ABOUT THE INSTALL CALL HOWE PERFORMANCE (619) 561-7764