
## **PROPER MARKING OF THE STEERING BOX FOR INTERNAL STOPS**

THE ACCURACY OF THE BOX INTERNAL SETUP IS COMPLETELY BASED ON THE ACCURACY OF THE PITMAN ARM MARKUP. TAKE YOUR TIME, DOUBLE CHECK YOUR WORK

NOTE: BEFORE MARKING THE STEERING BOX FOR INTERNAL STOPS, THE FOLLOWING THREE REQUIREMENTS MUST BE MET:

O THE FRONT WHEELS MUST BE POINTED STRAIGHT AHEAD AND ALIGNMENT BE CORRECT.
O THE STEERING BOX MUST BE CENTERED INTERNALLY .
O THE FLAT ON THE STEERING BOX INPUT SHAFT MUST BE AT THE TOP POSITION.

IF ANY OF THESE ARE NOT MET, IT MUST BE CORRECTED PRIOR TO MARKING THE BOX.



IF YOU HAVE ANY QUESTIONS ABOUT THE INSTALL CALL HOWE PERFORMANCE (619) 561-7764

STEERING BOX BASED ON THE ACCURACY OF THE PITMAN ARM MARKS.